



DFW Europe B.V.
Dulleweg 43
1721 PM Broek op Langedijk
The Netherlands
Tel: +31 226 342 909
Fax: +31 226 342 461
Mail: info@dfweurope.com

Monthly report for :

Cremator number : 1

Report for the month
starting : 01-05-2025

Total number of cremations =
150

Table 1 : Combustion Provisions - 5 min average

	PG/2 Criteria	Average value for period	Minimum value	Maximum value
Secondary Chamber Start Temperature °C	850°C unabated 800°C abated	912	828	1176
Secondary Chamber End Temperature °C	850°C unabated 800°C abated	887	757	1088
Oxygen % measured wet or dry	Average 6% Minimum 3%	12.0	1.8	18.3

Table 2 : 95th percentile emission value for period

Substance	95 percentile mp/m ³
Particulate matter unabated cremators only	N/A
Carbon monoxide all cremators	9.26

**Table 3 : Values that exceed the 95% limit (60 minute average) for:
Carbon monoxide and particulate on unabated plant
Carbon monoxide on abated plant operating to emission levels in PG5/2 (12) Table 4 item 4b**

Parameter	Value	Date	Time
N/A	N/A	N/A	N/A

Table 4 : 60 minute mean emission values that exceed 100% limit for carbon monoxide on all plants and particulate for unabated plant

Parameter	Value	Date	Time
N/A	N/A	N/A	N/A

Table 5 : Highest 60 minute mean emission value for the period

Parameter	Value	Date	Time
Carbon Monoxide (all cremators)	12.4	2020-05-19	09:36:01
Particulate (unabated cremators only)	N/A	N/A	N/A

Table 6 : Limit exceedances during the period

Number of Oxygen excursion below limit 4

Exceedances

Secondary Chamber Temperatures - 5 minute average below the minimum limit (850°C unabated, 800°C abated)

Oxygen - 5 minute averages below 3% wet or dry
- 60 minute averages below 6% wet or dry

Parameter	Value	Date	Time
Secondary Chamber < 800 °C	796	2020-05-11	08:02:14
Secondary Chamber < 800 °C	788	2020-05-11	08:07:26
Secondary Chamber < 800 °C	780	2020-05-11	08:12:38
Secondary Chamber < 800 °C	772	2020-05-11	08:17:41
Secondary Chamber < 800 °C	763	2020-05-11	08:22:44
Secondary Chamber < 800 °C	758	2020-05-11	08:27:44
Secondary Chamber < 800 °C	780	2020-05-11	08:32:44
Secondary Chamber < 800 °C	795	2020-05-11	08:37:44
Secondary Chamber < 800 °C	800	2020-05-11	08:47:53
O ₂ 5 min	2.8	2020-05-11	13:49:43
O ₂ 5 min	2.9	2020-05-11	13:54:52
O ₂ 5 min	1.9	2020-05-21	05:32:19
O ₂ 5 min	2.3	2020-05-21	11:31:03
O ₂ 5 min	2.5	2020-05-21	11:36:03



DFW Europe B.V.
Dulleweg 43
1721 PM Broek op Langedijk
The Netherlands
Tel: +31 226 342 909
Fax: +31 226 342 461
Mail: info@dfweurope.com



PERIOD : 01-05-2025 - 31-05-2025

11

START	STOP	DESCRIPTION
2016 12 28 10 55 18	2016 12 28 10 59 21	oven 2 Alarm Bypass
2016 12 28 10 55 18	2016 12 28 10 58 4	oven 2 Alarm Bypass Low Pressure Boiler
2016 12 28 10 46 1	2016 12 28 10 55 02	oven 2 Alarm Bypass
2016 12 28 9 46 30	2016 12 28 9 46 46	oven 2 Alarm Pressure MB
2016 12 26 15 36 26	2016 12 28 10 45 58	oven 2 Alarm Bypass
2016 12 26 15 36 26	2016 12 28 10 55 02	oven 2 Alarm Bypass Low Pressure Boiler
2016 12 12 9 28 09	2016 12 12 10 38 20	oven 2 Alarm Bypass
2016 12 12 9 2 35	2016 12 12 10 3 15	oven 2 Alarm Bypass Low Pressure Boiler
2016 12 05 10 41 38	2016 12 05 10 44 16	oven 2 Alarm Bypass Low Pressure Boiler
2016 12 05 5 00 45	2016 12 05 10 51 4	oven 2 Alarm Bypass
2016 12 05 5 00 45	2016 12 05 10 41 20	oven 2 Alarm Bypass Low Pressure Boiler